

## **I.6. Side play of the crankarms**

Please see also H.4.

If you hold the left and the right crankarm and try to wobble them in lateral direction, a play can indicate a worn out left industrial bearing (or an inadequate grooved nut on the left side, because it doesn't guide the left bearing correctly: please see F.16.6. for further explanations).

These industrial bearings have a life expectancy of 20'000 to 30'000 km.

Such a play can't be adjusted by the self locking nut!