

## **I.19. Drive skips every second or third crank revolution**

You may drive with too much chain tension! Please reduce tension and try again!